



Form No. 6873

PLANT SERVICE & MAINTENANCE REPORT

Work to be completed by a licensed mechanic

Date of Service	02/07/2026	Make	Yanmar
Asset	X56	Model	VI055-6B
Location of service	CMS Yard	Serial Number	BH676
Completed by	Aidan Mann	Hours	2461
Licence Number	MVTC142355	Service Due (hours)	2711

Work Required	500 hour service
---------------	------------------

Work Performed	500 hour service
----------------	------------------

Outstanding Work Required	None
---------------------------	------

Consumables/Oils/Grease					
Consumables	Rags, gloves	Hydraulic Oil	10	Grease	5
Engine Oil	10	Gear Oil		Coolant	
Trans Oil		Diff Oil		Enviro Costs	

Additional Job Notes	None
----------------------	------

Plant Safety Check - Please tick all that have been checked:			
✓	Lights, Warning Devices, Signs etc	✓	Condition of hoods, sheaves, chains
✓	Hydraulics - leaks damage connections	✓	Cabin - controls, loose objects, seat belts, windscreen visibility
✓	Components - damage, broken	✓	Warning lights / gauges
✓	Wheel/Tracks/Tyres - loose, nuts, wear	✓	Operation of brakes, steering, controls, wipers, levers, buckets
✓	Pins - pivots, rams, lift arms, bucket pins	✓	Other - eg: fire extinguisher, electrical connections, wires etc
✓	Guards - in place, secure, warnings	✓	Environmental Spill Kit complete & available
		✓	Plant Security

✓ VIP CHECK AROUND PLANT PRIOR TO COMPLETION

Travel Time		Field Labour	3	Total Kilometres	
-------------	--	--------------	----------	------------------	--

SIGN OFF: I accept that the service and/or inspection has been completed. All repairs are complete to a satisfactory standard. The times/quantities indicated above are correct.

Service Person Name:	Matthew Greenlees
Licence No:	MVTC142355
Signature:	



Form No. 5134

SERVICE & MAINTENANCE REPORT

Work to be completed by a licensed mechanic

Date of Service	05/01/2026	Make	
Asset	X56	Model	
Rego Nbr		Serial Number	BH676
Location of job	Yard	Hours/Odometer	2155
Completed by	Matthew Greenlees	Licence Number	Mvtc142355

Work Required	2000 hour service
---------------	-------------------

Work Performed	Service engineer oil and filter fuel filter air filter inner and outer cabin filter replace hydraulic oil and filter replace final drive oil grease nipples degrease engine
----------------	---

Outstanding Work Required	
---------------------------	--

Consumables/Oils/Grease					
Consumables	Gloves rags	Hydraulic Oil	30l s46	Grease	
Engine Oil		Gear Oil		Coolant	
Trans Oil		Diff Oil		Enviro Costs	

Additional Job Notes	
----------------------	--

Plant Safety Check - Please tick all that have been checked:			
✓	Lights, Warning Devices, Signs etc	✓	Condition of hoods, sheaves, chains
✓	Hydraulics - leaks damage connections	✓	Cabin - controls, loose objects, seat belts, windscreen visibility
✓	Components - damage, broken	✓	Warning lights / gauges
✓	Wheel/Tracks/Tyres - loose, nuts, wear	✓	Operation of brakes, steering, controls, wipers, levers, buckets
✓	Pins - pivots, rams, lift arms, bucket pins	✓	Other - eg: fire extinguisher, electrical connections, wires etc
✓	Guards - in place, secure, warnings		Environmental Spill Kit complete & available
			Plant Security

VIP CHECK AROUND PLANT PRIOR TO COMPLETION

Travel Time		Field Labour	4	Total Kilometers	
-------------	--	--------------	----------	------------------	--

SIGN OFF: I accept that the service and/or inspection has been completed. All repairs are complete to a satisfactory standard. The times/quantities indicated above are correct.

Service Person Name:	Matthew Greenlees
Licence No:	Mvtc142355
Signature:	