



Form No. 7450

PLANT - SERVICE & MAINTENANCE REPORT

Work to be completed by a licensed mechanic when servicing a CMS PLANT.

Date of Service	03/07/2026	Make	Takeuchi
Asset	X60	Model	TB215R
Location of service	North Epping	Serial Number	215002024
Hours	1012	Next Service Due (hours)	1250

Work Required	1000 hour service
---------------	-------------------

Work Performed	Change engine oil and filter, change air filters, change gear oil, clean radiator and check coolant, replace hydraulic oil and hydraulic filter, change fuel filter and clean water separator. Safety inspection
----------------	--

Outstanding Work Required	Lock out lever requires new gas strut
---------------------------	---------------------------------------

Consumables/Oils/Grease					
Consumables		Hydraulic Oil	16	Grease	1
Engine Oil	3	Gear Oil	1	Coolant	
Trans Oil		Diff Oil		Enviro Costs	

Additional Job Notes	
----------------------	--

Plant Safety Check - Please tick all that have been checked:			
✓	Lights, Warning Devices, Signs etc	✓	Condition of hoods, sheaves, chains
✓	Hydraulics - leaks damage connections	✓	Cabin - controls, loose objects, seat belts, windscreen visibility
✓	Components - damage, broken	✓	Warning lights / gauges
✓	Wheel/Tracks/Tyres - loose, nuts, wear	✓	Operation of brakes, steering, controls, wipers, levers, buckets
✓	Pins - pivots, rams, lift arms, bucket pins	✓	Other - eg: fire extinguisher, electrical connections, wires etc
✓	Guards - in place, secure, warnings	✓	Environmental Spill Kit complete & available
		✓	Plant Security

✓ VIP CHECK AROUND PLANT PRIOR TO COMPLETION

Travel Time	1	Field Labour	2	Total Kilometres	
-------------	----------	--------------	----------	------------------	--

SIGN OFF: I accept that the service and/or inspection has been completed. All repairs are complete to a satisfactory standard. The times/quantities indicated above are correct.

Service Person Name:	Adam Middleton
Licence No:	MVTC178431
Signature:	



Form No. 3559

SERVICE & MAINTENANCE REPORT

Work to be completed by a licensed mechanic

Date of Service	19/03/2025	Make	
Asset	X60	Model	
Rego Nbr		Serial Number	
Location of job	Silverwater	Hours/Odometer	754
Completed by	Connor Snell	Licence Number	Sean Dicker

Work Required	250 hour service
---------------	------------------

Work Performed	Change oil and filter, top up hydraulic oil, inspect hydraulics coolant and radiator, change fan belt as worn out, replace air filter grease, safety inspection
----------------	---

Outstanding Work Required	
---------------------------	--

Consumables/Oils/Grease				
Consumables	1	Hydraulic Oil	3	Grease 1
Engine Oil	4	Gear Oil		Coolant
Trans Oil		Diff Oil		Enviro Costs

Additional Job Notes	
----------------------	--

Plant Safety Check - Please tick all that have been checked:			
✓	Lights, Warning Devices, Signs etc	✓	Condition of hoods, sheaves, chains
✓	Hydraulics - leaks damage connections	✓	Cabin - controls, loose objects, seat belts, windscreen visibility
✓	Components - damage, broken	✓	Warning lights / gauges
✓	Wheel/Tracks/Tyres - loose, nuts, wear	✓	Operation of brakes, steering, controls, wipers, levers, buckets
✓	Pins - pivots, rams, lift arms, bucket pins	✓	Other - eg: fire extinguisher, electrical connections, wires etc
✓	Guards - in place, secure, warnings	✓	Environmental Spill Kit complete & available
		✓	Plant Security

✓ VIP CHECK AROUND PLANT PRIOR TO COMPLETION

Travel Time	1	Field Labour	2.5	Total Kilometers	
-------------	----------	--------------	------------	------------------	--

SIGN OFF: I accept that the service and/or inspection has been completed. All repairs are complete to a satisfactory standard. The times/quantities indicated above are correct.

Service Person Name:	Connor Snell
Licence No:	Sean Dicker
Signature:	