



Form No. 7453

PLANT - SERVICE & MAINTENANCE REPORT

Work to be completed by a licensed mechanic when servicing a CMS PLANT.

Date of Service	19/03/2026	Make	Case
Asset	X62	Model	Cx220c
Location of service	Yarramundi	Serial Number	DCH220D6NNEFJ1326
Hours	1019	Next Service Due (hours)	1500

Work Required	1000 hour service
---------------	-------------------

Work Performed	Service replace engine oil and filter replace air filter replace fuel filter replace slew oil top up hydraulic fluid grease machine
----------------	---

Outstanding Work Required	
---------------------------	--

Consumables/Oils/Grease					
Consumables	Gloves rags	Hydraulic Oil		Grease	
Engine Oil		Gear Oil		Coolant	
Trans Oil		Diff Oil		Enviro Costs	

Additional Job Notes	
----------------------	--

Plant Safety Check - Please tick all that have been checked:			
✓	Lights, Warning Devices, Signs etc	✓	Condition of hoods, sheaves, chains
✓	Hydraulics - leaks damage connections	✓	Cabin - controls, loose objects, seat belts, windscreen visibility
✓	Components - damage, broken	✓	Warning lights / gauges
✓	Wheel/Tracks/Tyres - loose, nuts, wear	✓	Operation of brakes, steering, controls, wipers, levers, buckets
✓	Pins - pivots, rams, lift arms, bucket pins	✓	Other - eg: fire extinguisher, electrical connections, wires etc
✓	Guards - in place, secure, warnings	✓	Environmental Spill Kit complete & available
		✓	Plant Security

✓ VIP CHECK AROUND PLANT PRIOR TO COMPLETION

Travel Time		Field Labour	3	Total Kilometres	
-------------	--	--------------	----------	------------------	--

SIGN OFF: I accept that the service and/or inspection has been completed. All repairs are complete to a satisfactory standard. The times/quantities indicated above are correct.

Service Person Name:	Matthew Greenlees
Licence No:	Mvtc142355
Signature:	



Form No. 5187

PLANT SERVICE & MAINTENANCE REPORT

Work to be completed by a licensed mechanic

Date of Service	15/01/2026	Make	Case
Asset	X62	Model	CX220C
Location of service	On Site - Greendale	Serial Number	DCH220D6NNEFJ1326
Completed by	Aidan Mann	Hours	882
Licence Number	MVTC142355	Service Due (hours)	1382

Work Required	250 hour service
---------------	------------------

Work Performed	250 hour service
----------------	------------------

Outstanding Work Required	None
---------------------------	------

Consumables/Oils/Grease					
Consumables	Rags and Gloves	Hydraulic Oil	10L	Grease	1
Engine Oil	17L	Gear Oil		Coolant	
Trans Oil		Diff Oil		Enviro Costs	

Additional Job Notes	
----------------------	--

Plant Safety Check - Please tick all that have been checked:			
✓	Lights, Warning Devices, Signs etc	✓	Condition of hoods, sheaves, chains
✓	Hydraulics - leaks damage connections	✓	Cabin - controls, loose objects, seat belts, windscreen visibility
✓	Components - damage, broken	✓	Warning lights / gauges
✓	Wheel/Tracks/Tyres - loose, nuts, wear	✓	Operation of brakes, steering, controls, wipers, levers, buckets
✓	Pins - pivots, rams, lift arms, bucket pins	✓	Other - eg: fire extinguisher, electrical connections, wires etc
✓	Guards - in place, secure, warnings	✓	Environmental Spill Kit complete & available
		✓	Plant Security

✓ VIP CHECK AROUND PLANT PRIOR TO COMPLETION

Travel Time	1.5	Field Labour	2	Total Kilometres	70
-------------	------------	--------------	----------	------------------	-----------

SIGN OFF: I accept that the service and/or inspection has been completed. All repairs are complete to a satisfactory standard. The times/quantities indicated above are correct.

Service Person Name:	Matthew Greenlees
Licence No:	MVTC142355
Signature:	