



Form No. 7460

PLANT - SERVICE & MAINTENANCE REPORT

Work to be completed by a licensed mechanic when servicing a CMS PLANT.

Date of Service	15/08/2026	Make	Kubota
Asset	X47	Model	N/a
Location of service	Workshop	Serial Number	N/a
Hours	4290	Next Service Due (hours)	4800

Work Required	500 hour service
---------------	------------------

Work Performed	Serviced drives as well
----------------	-------------------------

Outstanding Work Required	E stop wiring on bonnet needs to be fixxed
---------------------------	--

Consumables/Oils/Grease					
Consumables	Rags and brake cleaner	Hydraulic Oil	5 ltrs	Grease	1 tube
Engine Oil	10 ltrs	Gear Oil	5 ltrs	Coolant	
Trans Oil		Diff Oil		Enviro Costs	

Additional Job Notes	
----------------------	--

Plant Safety Check - Please tick all that have been checked:			
✓	Lights, Warning Devices, Signs etc	✓	Condition of hoods, sheaves, chains
✓	Hydraulics - leaks damage connections	✓	Cabin - controls, loose objects, seat belts, windscreen visibility
✓	Components - damage, broken	✓	Warning lights / gauges
✓	Wheel/Tracks/Tyres - loose, nuts, wear	✓	Operation of brakes, steering, controls, wipers, levers, buckets
✓	Pins - pivots, rams, lift arms, bucket pins	✓	Other - eg: fire extinguisher, electrical connections, wires etc
✓	Guards - in place, secure, warnings	✓	Environmental Spill Kit complete & available
		✓	Plant Security

✓ VIP CHECK AROUND PLANT PRIOR TO COMPLETION

Travel Time		Field Labour		Total Kilometres	
-------------	--	--------------	--	------------------	--

SIGN OFF: I accept that the service and/or inspection has been completed. All repairs are complete to a satisfactory standard. The times/quantities indicated above are correct.

Service Person Name:	Adam Middleton
Licence No:	0
Signature:	



Form No. 5227

SERVICE & MAINTENANCE REPORT

Work to be completed by a licensed mechanic

Date of Service	20/01/2026	Make	
Asset	X47	Model	
Rego Nbr		Serial Number	0
Location of job	Yard	Hours/Odometer	4000
Completed by	Matthew Greenlees	Licence Number	Mvtc142355

Work Required	2000 hour service
---------------	-------------------

Work Performed	Service engine oil and filter fuel filter air filter inner and outer replace hydraulic oil and filters replace hydraulic breather filter grease nipples replace drive oil
----------------	---

Outstanding Work Required	
---------------------------	--

Consumables/Oils/Grease					
Consumables	Gloves rags	Hydraulic Oil		Grease	1
Engine Oil	11	Gear Oil		Coolant	
Trans Oil		Diff Oil	2	Enviro Costs	

Additional Job Notes	
----------------------	--

Plant Safety Check - Please tick all that have been checked:			
✓	Lights, Warning Devices, Signs etc	✓	Condition of hoods, sheaves, chains
✓	Hydraulics - leaks damage connections		Cabin - controls, loose objects, seat belts, windscreen visibility
✓	Components - damage, broken		Warning lights / gauges
✓	Wheel/Tracks/Tyres - loose, nuts, wear		Operation of brakes, steering, controls, wipers, levers, buckets
✓	Pins - pivots, rams, lift arms, bucket pins		Other - eg: fire extinguisher, electrical connections, wires etc
✓	Guards - in place, secure, warnings		Environmental Spill Kit complete & available
			Plant Security

VIP CHECK AROUND PLANT PRIOR TO COMPLETION

Travel Time		Field Labour	4	Total Kilometers	
-------------	--	--------------	----------	------------------	--

SIGN OFF: I accept that the service and/or inspection has been completed. All repairs are complete to a satisfactory standard. The times/quantities indicated above are correct.

Service Person Name:	Matthew Greenlees
Licence No:	Mvtc142355
Signature:	



Form No. 4043

SERVICE & MAINTENANCE REPORT

Work to be completed by a licensed mechanic

Date of Service	22/07/2025	Make	
Asset	X47	Model	
Rego Nbr		Serial Number	
Location of job	Silverwater	Hours/Odometer	3845
Completed by	Matthew Greenlees	Licence Number	Matt Greenlees

Work Required	250 hour service
---------------	------------------

Work Performed	Change engine oil and filter, blow out air filters, grease, degrease, clean ad check fluid levels
----------------	---

Outstanding Work Required	
---------------------------	--

Consumables/Oils/Grease					
Consumables		Hydraulic Oil	10	Grease	1
Engine Oil	10	Gear Oil		Coolant	
Trans Oil		Diff Oil		Enviro Costs	

Additional Job Notes	
----------------------	--

Plant Safety Check - Please tick all that have been checked:			
✓	Lights, Warning Devices, Signs etc	✓	Condition of hoods, sheaves, chains
✓	Hydraulics - leaks damage connections	✓	Cabin - controls, loose objects, seat belts, windscreen visibility
✓	Components - damage, broken	✓	Warning lights / gauges
✓	Wheel/Tracks/Tyres - loose, nuts, wear	✓	Operation of brakes, steering, controls, wipers, levers, buckets
✓	Pins - pivots, rams, lift arms, bucket pins	✓	Other - eg: fire extinguisher, electrical connections, wires etc
✓	Guards - in place, secure, warnings	✓	Environmental Spill Kit complete & available
		✓	Plant Security

✓ VIP CHECK AROUND PLANT PRIOR TO COMPLETION

Travel Time		Field Labour	3	Total Kilometers	
-------------	--	--------------	----------	------------------	--

SIGN OFF: I accept that the service and/or inspection has been completed. All repairs are complete to a satisfactory standard. The times/quantities indicated above are correct.

Service Person Name:	Matthew Greenlees
Licence No:	Matt Greenlees
Signature:	



Form No. 2776

SERVICE & MAINTENANCE REPORT

Work to be completed by a licensed mechanic

Date of Service	13/09/2024	Make	
Asset	X47	Model	
Rego Nbr		Serial Number	
Location of job	Yard	Hours/Odometer	3494
Completed by	Trenton Van Loon	Licence Number	Trenton van Loon

Work Required	500 hour service
---------------	------------------

Work Performed	Engine oil and filter. Fuel filters. Hydraulic oil checked - ok. Final drive oil checked. Ok. Fan belt checked and adjusted. Machine greased. Track tesnion checked and adjusted - ok. Cab items checked - ok. Check airfilters- ok. Topped up radiator and checked condition- find bent but ok.
----------------	--

Outstanding Work Required	
---------------------------	--

Consumables/Oils/Grease				
Consumables	Rags, brake cleaner, gloves	Hydraulic Oil		Grease 1
Engine Oil	8	Gear Oil		Coolant
Trans Oil		Diff Oil		Enviro Costs

Additional Job Notes	
----------------------	--

Plant Safety Check - Please tick all that have been checked:			
✓	Lights, Warning Devices, Signs etc	✓	Condition of hoods, sheaves, chains
✓	Hydraulics - leaks damage connections	✓	Cabin - controls, loose objects, seat belts, windscreen visibility
✓	Components - damage, broken	✓	Warning lights / gauges
✓	Wheel/Tracks/Tyres - loose, nuts, wear	✓	Operation of brakes, steering, controls, wipers, levers, buckets
✓	Pins - pivots, rams, lift arms, bucket pins	✓	Other - eg: fire extinguisher, electrical connections, wires etc
✓	Guards - in place, secure, warnings	✓	Environmental Spill Kit complete & available
		✓	Plant Security

✓ **VIP CHECK AROUND PLANT PRIOR TO COMPLETION**

Travel Time		Field Labour	3.5	Total Kilometers	
-------------	--	--------------	------------	------------------	--

SIGN OFF: I accept that the service and/or inspection has been completed. All repairs are complete to a satisfactory standard. The times/quantities indicated above are correct.

Service Person Name:	Trenton Van Loon
Licence No:	Trenton van Loon
Signature:	