



Form No. 7966

PLANT - SERVICE & MAINTENANCE REPORT

Work to be completed by a licensed mechanic when servicing a CMS PLANT.

Date of Service	09/09/2026	Make	Yanmar
Asset	X66	Model	VIO55-6B
Location of service	Silverwater	Serial Number	BJ796
Hours	1201	Next Service Due (hours)	1450

Work Required	250 hour service
---------------	------------------

Work Performed	250 hour service
----------------	------------------

Outstanding Work Required	None
---------------------------	------

Consumables/Oils/Grease					
Consumables	Gloves, rags	Hydraulic Oil	20	Grease	2
Engine Oil	10	Gear Oil		Coolant	
Trans Oil		Diff Oil		Enviro Costs	

Additional Job Notes	
----------------------	--

Plant Safety Check - Please tick all that have been checked:			
✓	Lights, Warning Devices, Signs etc	✓	Condition of hoods, sheaves, chains
✓	Hydraulics - leaks damage connections	✓	Cabin - controls, loose objects, seat belts, windscreen visibility
✓	Components - damage, broken	✓	Warning lights / gauges
✓	Wheel/Tracks/Tyres - loose, nuts, wear	✓	Operation of brakes, steering, controls, wipers, levers, buckets
✓	Pins - pivots, rams, lift arms, bucket pins	✓	Other - eg: fire extinguisher, electrical connections, wires etc
✓	Guards - in place, secure, warnings	✓	Environmental Spill Kit complete & available
		✓	Plant Security

✓ VIP CHECK AROUND PLANT PRIOR TO COMPLETION

Travel Time		Field Labour	2	Total Kilometres	
-------------	--	--------------	----------	------------------	--

SIGN OFF: I accept that the service and/or inspection has been completed. All repairs are complete to a satisfactory standard. The times/quantities indicated above are correct.

Service Person Name:	Matthew Greenlees
Licence No:	MTVC142355
Signature:	



Form No. 7967

PLANT - SERVICE & MAINTENANCE REPORT

Work to be completed by a licensed mechanic when servicing a CMS PLANT.

Date of Service	27/03/2026	Make	Yanmar
Asset	X66	Model	VIO55-6B
Location of service	Silverwater	Serial Number	BJ796
Hours	962	Next Service Due (hours)	1212

Work Required	1000 hour service
---------------	-------------------

Work Performed	1000 hour service
----------------	-------------------

Outstanding Work Required	None
---------------------------	------

Consumables/Oils/Grease					
Consumables	Rags, gloves	Hydraulic Oil	25	Grease	3
Engine Oil	12	Gear Oil		Coolant	
Trans Oil		Diff Oil		Enviro Costs	

Additional Job Notes	
----------------------	--

Plant Safety Check - Please tick all that have been checked:			
✓	Lights, Warning Devices, Signs etc	✓	Condition of hoods, sheaves, chains
✓	Hydraulics - leaks damage connections	✓	Cabin - controls, loose objects, seat belts, windscreen visibility
✓	Components - damage, broken	✓	Warning lights / gauges
✓	Wheel/Tracks/Tyres - loose, nuts, wear	✓	Operation of brakes, steering, controls, wipers, levers, buckets
✓	Pins - pivots, rams, lift arms, bucket pins	✓	Other - eg: fire extinguisher, electrical connections, wires etc
✓	Guards - in place, secure, warnings	✓	Environmental Spill Kit complete & available
		✓	Plant Security

✓ VIP CHECK AROUND PLANT PRIOR TO COMPLETION

Travel Time		Field Labour	3	Total Kilometres	
-------------	--	--------------	----------	------------------	--

SIGN OFF: I accept that the service and/or inspection has been completed. All repairs are complete to a satisfactory standard. The times/quantities indicated above are correct.

Service Person Name:	Matthew Greenlees
Licence No:	MTVC142355
Signature:	